

ABSTRACT OF THE DISCLOSURE

Sub
B 1
5

A brushless electric machine uses a signal of the flux-causing voltage across the or each phase winding for control. Flux is more closely related to machine torque than current control, thus providing more accurate control.

0973646 121500